


CanFarm 1

Summerville

Clubhouse Road, Summerville, Dorchester, SC, USA

12.0 Acres



CanFarm 1

Soil Report

Symbol	Map Unit Description	Farmland class	Area (AC)	Available Water Storage (0-150cm - Weighted Average)	Flooding Frequency (Maximum)	Drainage Class (Dominant Condition)	Drainage Class (Wettest Component)	Hydric Classification	Water Table Depth (Annual Minimum)	Water Table Depth (April to June Minimum)	Bedrock Depth (Minimum)	Soil Order
CoB	Chisolm fine sand, 0 to 6 percent slopes	Farmland of statewide importance	0	12.7	None	Well drained	Well drained	2	122	0	0	Ultisols
Hp	Haplaquents, loamy	Not prime farmland	0	21.0	None	Moderately well drained	Moderately well drained	100	15	15	0	Entisols
Mo	Mouzon fine sandy loam, occasionally flooded	Farmland of statewide importance	0	19.8	Occasional	Poorly drained	Poorly drained	98	15	15	0	Alfisols
Cs	Coosaw loamy fine sand	Farmland of statewide importance	0	16.0	None	Moderately well drained	Moderately well drained	2	76	0	0	Ultisols
YaA	Yauhannah loamy fine sand, 0 to 2 percent slopes	All areas are prime farmland	0	18.5	None	Moderately well drained	Moderately well drained	3	61	0	0	Ultisols
Ye	Yemassee fine sandy loam	Prime farmland if drained	0	21.3	None	Somewhat poorly drained	Somewhat poorly drained	4	38	0	0	Ultisols